To: Ex. 6 - Personal Privacy
Cc: Durno, Mark[durno.mark@epa.gov]

Cc: Durno, Mark[durno.mark@ From: Scott Smith

Sent: Wed 5/10/2017 3:19:10 PM
Subject: Joint EPA / Water Defense Testing

704552 Bacteria Report.pdf
House 1704552 Report.pdf

Zelikoff Bacteria from Water Defense Testing with EPA.pdf

Dear Ex. 6 - Personal Privacy

Attached are the analytical reports from recent testing conducted by Water Defense. Also, I've included a chlorine monitoring summary that was provided by EPA. Please let me know if you have any questions. If you have any questions about the chlorine results, please contact Mark Durno, EPA, at 440-250-1743.

- First attachment is the bacteria report for your house (highlighted in yellow) and the non highlighted portions show bacteria found in the other homes tested. These tests are done with Q Laboratories using approved sponge testing methods.
- Second attachment is the report from our outside lab on the testing for chemicals.
 Please note that tests with the grab samples use are taken in accordance with
 approved EPA methods. The WaterBug testing for chemicals is used for research
 purposes and is not currently an approved EPA method. The WaterBug testing is
 for research and intended to identify the presence of chemicals and the results
 cannot be used to determine compliance with any current regulations.
- Third attachment is a summary of the bacteria found in all 4 homes.

EPA chlorine data is below:

All monitoring results were collected using a Hach II Pocket Colorimeter and field checked with blank and 1 mg/L standards prior to samples being collected. Reagent used is for free chlorine. Hach test strips (free & total chlorine) were also used to screen prior to collecting monitor samples. Note: This summary contains personally identifiable information (PII) and should not be disclosed to the open public without first redacting the PII.

E. Wellington Avenue Ex. 6-Personal Privacy residence)

Time: 15:00 hours

Location: Bathroom sink

Result: 0.13 mg/L free chlorine

Note: Home has a whole house filter. 5 minute flush conducted prior to

sample collection.

Location: Pre-filter valve (basement)

Result: Approximately 0.5 mg/L free and total chlorine. No flushing conducted, minimal water use prior to collection.

Note: Result is from second strip after minimal water flow. The first strip (stagnant water) showed no chlorine.

Best Regards,

Scott C. Smith Cell (508) 345-6520

Twitter: @WaterWarriorOne